



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Report of Analysis

Client:	Inframark	Date Collected:	06/08/22 07:00
Project:	Fresh Kills Landfill Leachate Treatment Plant	Date Received:	06/08/22
Client Sample ID:	BI-WEEKLY-INFLUENT	SDG No.:	N3259
Lab Sample ID:	N3259-01	Matrix:	WATER
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	1480	OR	10	0.97	6.00	mg/L		06/09/22 13:23	300.0
COD	437	D	10	24.0	100	mg/L		06/10/22 14:17	SM5220 D
Phosphorus, Total	1.27	OR	1	0.010	0.050	mg/L	06/09/22 09:45	06/09/22 14:22	365.3

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits