



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Initial and Continuing Calibration Verification

Client: LiRo Engineers, Inc.

SDG No.: P1747

Project: Walter Gladwin Recreation Center, Bronx, NY

RunNo.: LB129879

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV						
Flash Point	o F	81.7	81	101	78-84	03/14/2024



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Initial and Continuing Calibration Verification

Client: LiRo Engineers, Inc.

SDG No.: P1747

Project: Walter Gladwin Recreation Center, Bronx, NY

RunNo.: LB129881

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Hexavalent Chromium	mg/L	0.502	0.5	100	95-105	03/14/2024
Sample ID: CCV1 Hexavalent Chromium	mg/L	0.500	0.5	100	90-110	03/14/2024
Sample ID: CCV2 Hexavalent Chromium	mg/L	0.502	0.5	100	90-110	03/14/2024



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Initial and Continuing Calibration Verification

Client: LiRo Engineers, Inc.

SDG No.: P1747

Project: Walter Gladwin Recreation Center, Bronx, NY

RunNo.: LB129910

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Phenolics	ICV1	mg/L	0.97	1	97	90-110	03/15/2024
Sample ID: Phenolics	CCV1	mg/L	0.98	1	98	90-110	03/15/2024
Sample ID: Phenolics	CCV2	mg/L	1	1	100	90-110	03/15/2024

Initial and Continuing Calibration Verification**Client:** LiRo Engineers, Inc.**SDG No.:** P1747**Project:** Walter Gladwin Recreation Center, Bronx, NY**RunNo.:** LB129942

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV1						
TKN		mg/L	4.8	5	96	90-110	03/19/2024
Sample ID:	CCV1						
TKN		mg/L	4.8	5	96	90-110	03/19/2024
Sample ID:	CCV2						
TKN		mg/L	4.9	5	98	90-110	03/19/2024
Sample ID:	CCV3						
TKN		mg/L	5	5	100	90-110	03/19/2024