



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Initial and Continuing Calibration Blank Summary

Client: LiRo Engineers, Inc.

SDG No.: P1747

Project: Walter Gladwin Recreation Center, Bronx, NY

RunNo.: LB129881

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
Sample ID: ICB Hexavalent Chromium	mg/L	< 0.0050	0.0050	U	0.0021	0.01	03/14/2024
Sample ID: CCB1 Hexavalent Chromium	mg/L	< 0.0050	0.0050	U	0.0021	0.01	03/14/2024
Sample ID: CCB2 Hexavalent Chromium	mg/L	< 0.0050	0.0050	U	0.0021	0.01	03/14/2024



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Initial and Continuing Calibration Blank Summary

Client: LiRo Engineers, Inc.

SDG No.: P1747

Project: Walter Gladwin Recreation Center, Bronx, NY

RunNo.: LB129910

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
Sample ID: ICB1 Phenolics	mg/L	< 0.0250	0.0250	U	0.012	0.05	03/15/2024
Sample ID: CCB1 Phenolics	mg/L	< 0.0250	0.0250	U	0.012	0.05	03/15/2024
Sample ID: CCB2 Phenolics	mg/L	< 0.0250	0.0250	U	0.012	0.05	03/15/2024



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Initial and Continuing Calibration Blank Summary

Client: LiRo Engineers, Inc.

SDG No.: P1747

Project: Walter Gladwin Recreation Center, Bronx, NY

RunNo.: LB129942

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
Sample ID: ICB1 TKN	mg/L	< 0.2500	0.2500	U	0.13	0.5	03/19/2024
Sample ID: CCB1 TKN	mg/L	< 0.2500	0.2500	U	0.13	0.5	03/19/2024
Sample ID: CCB2 TKN	mg/L	< 0.2500	0.2500	U	0.13	0.5	03/19/2024
Sample ID: CCB3 TKN	mg/L	< 0.2500	0.2500	U	0.13	0.5	03/19/2024