

Preparation Blank Summary

Client: LiRo Engineers, Inc.

SDG No.: P1747

Project: Walter Gladwin Recreation Center, Bronx, NY

Analyte	Units	Result	Acceptance Limits	Conc Qual	MDL	RDL	Analysis Date
Sample ID: LB129875BL CBOD5	mg/L	< 0.2000	0.2000	U	0.17	2.0	03/14/2024
Sample ID: LB129881BL Hexavalent Chromium	mg/L	< 0.0050	0.0050	U	0.002	0.01	03/14/2024
Sample ID: LB129888BL TS	mg/L	1	2.5000	J	1	5	03/14/2024
Sample ID: LB129890BL Chloride	mg/L	< 2.5000	2.5000	U	0.54	5.0	03/14/2024
Sample ID: LB129904BL Non-Polar Material	mg/L	< 2.5000	2.5000	U	0.53	5.0	03/15/2024
Sample ID: LB129917BL TSS	mg/L	1	2.0000	J	1	4	03/18/2024
Sample ID: PB159614BL TKN	mg/L	< 0.2500	0.2500	U	0.13	0.5	03/19/2024
Sample ID: PB159616BL Phenolics	mg/L	< 0.0250	0.0250	U	0.012	0.05	03/15/2024