



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Laboratory Control Sample Summary

Client:

LiRo Engineers, Inc.

SDG No.:

P1747

Project:

Walter Gladwin Recreation Center, Bronx, NY

Run No.:

LB129875

Analyte		Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	LB129875BS								
CBOD5		mg/L	198	175		88	1	84.6-115.4	03/14/2024



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Laboratory Control Sample Summary

Client:

LiRo Engineers, Inc.

SDG No.:

P1747

Project:

Walter Gladwin Recreation Center, Bronx, NY

Run No.:

LB129881

Analyte	Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	LB129881BS							
Hexavalent Chromium	mg/L	0.5	0.51		103	1	90-111	03/14/2024



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Laboratory Control Sample Summary

Client:

LiRo Engineers, Inc.

SDG No.:

P1747

Project:

Walter Gladwin Recreation Center, Bronx, NY

Run No.:

LB129890

Analyte		Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	LB129890BS								
Chloride		mg/L	50	47.0		94	1	90-110	03/14/2024



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Laboratory Control Sample Summary

Client:

LiRo Engineers, Inc.

SDG No.:

P1747

Project:

Walter Gladwin Recreation Center, Bronx, NY

Run No.:

LB129904

Analyte	Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	LB129904BS							
Non-Polar Material	mg/L	20.0	16.7		84	1	78-114	03/15/2024



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Laboratory Control Sample Summary

Client:

LiRo Engineers, Inc.

SDG No.:

P1747

Project:

Walter Gladwin Recreation Center, Bronx, NY

Run No.:

LB129904

Analyte	Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	LB129904BSD							
Non-Polar Material	mg/L	20.0	17.0		85	1	78-114	03/15/2024



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Laboratory Control Sample Summary

Client:

LiRo Engineers, Inc.

SDG No.:

P1747

Project:

Walter Gladwin Recreation Center, Bronx, NY

Run No.:

LB129917

Analyte		Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	LB129917BS								
TSS		mg/L	550	531		96	1	90-110	03/18/2024



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Laboratory Control Sample Summary

Client:

LiRo Engineers, Inc.

SDG No.:

P1747

Project:

Walter Gladwin Recreation Center, Bronx, NY

Run No.:

LB129942

Analyte		Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	PB159614BS								
TKN		mg/L	5	4.80		96	1	90-110	03/19/2024



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Laboratory Control Sample Summary

Client:

LiRo Engineers, Inc.

SDG No.:

P1747

Project:

Walter Gladwin Recreation Center, Bronx, NY

Run No.:

LB129910

Analyte		Units	True Value	Result	Conc. Qualifier	% Recovery	Dilution Factor	Acceptance Limit %R	Analysis Date
Sample ID	PB159616BS								
Phenolics		mg/L	1	0.97		97	1	80-120	03/15/2024