



284 Sheffield Street, Mountainside, New Jersey - 07092

Phone: (908) 789 8900 Fax: (908) 789 8922

LAB CHRONICLE

OrderID: P1747	OrderDate: 3/13/2024 12:28:00 PM
Client: LiRo Engineers, Inc.	Project: Walter Gladwin Recreation Center, Bronx, NY
Contact: Steve Frank	Location: I21,I31,VOA Ref. #3 Water

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P1747-01	MW-01	Water	Mercury	7470A	03/12/24	03/15/24	03/19/24	03/13/24
			Metals ICP-TAL	6010D		03/14/24	03/18/24	
P1747-02	MW-01-DUP	Water	Mercury	7470A	03/12/24	03/15/24	03/19/24	03/13/24
			Metals ICP-TAL	6010D		03/14/24	03/18/24	
P1747-03	MW-01	Water	Mercury	245.1	03/13/24	03/20/24	03/20/24	03/13/24
			METALS-NYCD	200.7		03/14/24	03/21/24	
P1747-04	MW-02	Water	Mercury	7470A	03/12/24	03/15/24	03/19/24	03/13/24
			Metals ICP-TAL	6010D		03/14/24	03/18/24	
P1747-05	TWP-04	Water	Mercury	7470A	03/12/24	03/15/24	03/19/24	03/13/24
			Metals ICP-TAL	6010D		03/14/24	03/18/24	
P1747-07	MW-01	Water	Dissolved ICP-TAL Metals	6010D	03/12/24	03/14/24	03/18/24	03/13/24
			Dissolved Mercury	7470A		03/15/24	03/19/24	
P1747-08	MW-01-DUP	Water	Dissolved ICP-TAL Metals	6010D	03/12/24	03/14/24	03/18/24	03/13/24
			Dissolved Mercury	7470A		03/15/24	03/19/24	
P1747-09	MW-02	Water	Dissolved ICP-TAL Metals	6010D	03/12/24	03/14/24	03/18/24	03/13/24
			Dissolved Mercury	7470A		03/15/24	03/19/24	
P1747-10	TWP-04	Water			03/12/24			03/13/24



284 Sheffield Street, Mountainside, New Jersey - 07092

Phone: (908) 789 8900 Fax: (908) 789 8922

LAB CHRONICLE

Dissolved ICP-TAL Metals	6010D	03/14/24	03/18/24
Dissolved Mercury	7470A	03/15/24	03/19/24