

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: JACOBS Engineering Group, Inc. Date Collected: 07/31/24 Project: Former Schlumberger Site Princeton NJ Date Received: 07/31/24 Client Sample ID: 927-K1-WS-073124-FD SDG No.: P3426 Lab Sample ID: P3426-02 Matrix: Water Level (low/med): low % Solid: 0

Cas	Parameter	Conc.	Qua. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
Dissolved	Dissolved	7550	1 64.0	428	ug/L	10/24/24 11:45	10/24/24 21:32	EPA 200.7	7
Silica	Silica								

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group5

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits