

## LAB CHRONICLE

|                 |                                |                   |                                       |
|-----------------|--------------------------------|-------------------|---------------------------------------|
| <b>OrderID:</b> | P3429                          | <b>OrderDate:</b> | 7/31/2024 4:38:00 PM                  |
| <b>Client:</b>  | JACOBS Engineering Group, Inc. | <b>Project:</b>   | Former Schlumberger Site Princeton NJ |
| <b>Contact:</b> | Mary I. Murphy                 | <b>Location:</b>  | D31,VOA Ref. #3 Water                 |

| LabID    | ClientID         | Matrix | Test           | Method        | Sample Date | Prep Date | Anal Date | Received |
|----------|------------------|--------|----------------|---------------|-------------|-----------|-----------|----------|
| P3429-01 | 926-K1-WS-073124 | Water  | SVOCMS Group6  | 8270E         | 07/31/24    | 08/01/24  | 08/07/24  | 07/31/24 |
|          |                  |        | SVOC-SIMGroup1 | 8270-Modified |             | 08/01/24  | 08/03/24  |          |
| P3429-02 | 931-K1-WS-073124 | Water  | SVOCMS Group6  | 8270E         | 07/31/24    | 08/01/24  | 08/07/24  | 07/31/24 |
|          |                  |        | SVOC-SIMGroup1 | 8270-Modified |             | 08/01/24  | 08/03/24  |          |
| P3429-03 | 925-K1-WS-073124 | Water  | SVOCMS Group6  | 8270E         | 07/31/24    | 08/01/24  | 08/07/24  | 07/31/24 |
|          |                  |        | SVOC-SIMGroup1 | 8270-Modified |             | 08/01/24  | 08/03/24  |          |