

Silica

Silica

## **Report of Analysis**

Client:		JAC	JACOBS Engineering Group, Inc.					: 08/0	2/24		
Project:		Form	ner Schlumb	erger Site I	Princeton NJ	Date Received	. 08/0	08/02/24			
Client Sample ID:		919-	919-J-WS-080224					P3467			
Lab San	nple ID:	P346	67-01				Matrix:	Wate	er		
Level (low/med):		low					% Solid:	0			J
Cas	Parameter	Conc.	Qua. DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Me	et.
Dissolved	Dissolved	6830	1	64.0	428	ug/L	10/24/24 11:45	10/24/24 22:03	EPA 200.7	7	

Color Before:	Colorless	Clarity Before:	Clear	Texture:			
Color After:	Colorless	Clarity After:	Clear	Artifacts:			
Comments: Metals Group5							
U = Not Detection	U = Not Detected			J = Estimated Value			
LOQ = Limit	of Quantitation			B = Analyte Found in Associated Method Blank			
MDL = Metho	d Detection Limit			* = indicates the duplicate analysis is not within control limits.			
LOD = Limit	of Detection			E = Indicates the reported value is estimated because of the presence			
D = Dilution				of interference.			
Q = indicates	LCS control criteria did not me	et requirements		OR = Over Range			

N =Spiked sample recovery not within control limits