## DATA OF KNOWN QUALITY CONFORMANCE/NON-CONFORMANCE SUMMARY QUESTIONNAIRE

Laboratory Name : Alliance Technical Group		Client :	JACOBS Engineering Group, Inc.			
Project Location :	Princeton Junction, NJ	Project Number :	D3779922			
Laboratory Sample ID	9(s) : <u>P3573</u>	Sampling Date(s) :	08/09/2024			
List DKQP Methods Used (e.g., 8260.8270, et Cetra)		6010D.8270E				

□ Yes ☑ No

1	For each analytical method referenced in this laboratory report package, were all specified QA/QC performance criteria followed, including the requirement to explain any criteria falling outside of acceptable guidelines, as specified in the NJDEP Data of Known Quality performance standards?	Ń	Yes		No	
1A	Were the method specified handling, preservation, and holding time requirements met?	Ŋ	Yes		No	
1B	EPH Method: Was the EPH method conducted without significant modifications (see Section 11.3 of respective DKQ methods)		Yes		No	☑ N/A
2	Were all samples received by the laboratory in a condition consistent with that described on the associated chain-of-custody document(s)?	$\mathbf{N}$	Yes		No	
3	Were samples received at an appropriate temperature (4±2° C)?	V	Yes		No	□ N/A
4	Were all QA/QC performance criteria specified in the NJDEP DKQP standards achieved?		Yes	V	No	
5	a)Were reporting limits specified or referenced on the chain-of-custody or communicated to the laboratory prior to sample receipt?	V	Yes		No	
	b)Were these reporting limits met?	$\checkmark$	Yes		No	□ N/A
6	For each analytical method referenced in this laboratory report package, were results reported for all constituents identified in the method-specific analyte lists presented in the DKQP documents and/or site-specific QAPP?	V	Yes		No	

Notes: For all questions to which the response was "No" (with the exception of question #7), additional information should be provided in an attached narrative. If the answer to question #1, #1A, or #1B is "No", the data package does not meet the requirements for "Data of Known Quality."

Are project-specific matrix spikes and/or laboratory duplicates included in this data set?

7



## **Cover Page**

- Order ID : P3573
- Project ID : Former Schlumberger Site Princeton NJ
  - **Client :** JACOBS Engineering Group, Inc.

## Lab Sample Number **Client Sample Number** P3573-01 S-858-KI-SO-2-2.5-080924 P3573-02 S-859-KI-SO-2-2.5-080924 P3573-03 S-859-KI-SO-2-2.5-080924-FD P3573-04 S-860-KI-SO-2-2.5-080924 P3573-05 S-856-J-SO-1-1.5-080924 P3573-06 S-856-J-SO-1-1.5-080924-FD P3573-07 S-856-J-SO-1.5-2-080924 P3573-08 S-856-J-SO-2-2.5-080924 P3573-09 S-856-J-SO-3-3.5-080924 P3573-10 S-856-J-SO-4-4.5-080924 P3573-12 EB-01-080924

I certify that the data package is in compliance with the terms and conditions of the contract, both technically and for completeness, for other than the conditions detailed above. Release of the data contained in this hard copy data package has been authorized by the laboratory manager or his designee, as verified by the following signature.

Signature :

Date: 6/3/2025

NYDOH CERTIFICATION NO - 11376

NJDEP CERTIFICATION NO - 20012