## DATA OF KNOWN QUALITY CONFORMANCE/NON-CONFORMANCE SUMMARY QUESTIONNAIRE

Laboratory Name : A		Alliance Technical Group LLC	Client :	JACOBS Engineering Group, Inc.					
Project Location : Princeton Junction, NJ Pro			Project Number :	D3779922					
Laboratory Sample ID(s): P3645 Sampling Date(s): 8/15/2024									
List DI	List DKQP Methods Used (e.g., 8260,8270, et Cetra) <b>6020B,7196A,7470A,8260D,8270-Modified,8270E, 200.7</b>								
1	specified QA/C explain any crit	tical method referenced in this lab C performance criteria followed, i teria falling outside of acceptable of f Known Quality performance stan	ncluding the requirement to guidelines, as specified in the		$\overline{\mathbf{N}}$	Yes		No	
1A	Were the method specified handling, preservation, and holding time requirements met?					Yes		No	
1B	EPH Method: Was the EPH method conducted without significant modifications (see Section 11.3 of respective DKQ methods)					Yes		No	✓ N/A
2	Were all samples received by the laboratory in a condition consistent with that described on the associated chain-of-custody document(s)?			V	Yes		No		
3	Were samples	received at an appropriate temper	rature (4±2° C)?		$\overline{\mathbf{A}}$	Yes		No	□ N/A
4	Were all QA/QC performance criteria specified in the NJDEP DKQP standards achieved?				Yes	$\overline{\checkmark}$	No		
5		ng limits specified or referenced o to the laboratory prior to sample i			V	Yes		No	
	b)Were these r	reporting limits met?			V	Yes		No	□ N/A
6	results reporte	rtical method referenced in this labed for all constituents identified in e DKQP documents and/or site-sp	the method-specific analyte		V	Yes		No	
7	Are project-spe	ecific matrix spikes and/or laborate	ory duplicates included in this	s data set?		Yes	<b>V</b>	No	

Notes: For all questions to which the response was "No" (with the exception of question #7), additional information should be provided in an attached narrative. If the answer to question #1, #1A, or #1B is "No", the data package does not meet the requirements for "Data of Known Quality."



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## **Cover Page**

Order ID: P3645

**Project ID:** Former Schlumberger Site Princeton NJ

**Client:** JACOBS Engineering Group, Inc.

## Lab Sample Number Client Sample Number

P3645-01 914-J-WS-081524 P3645-02 916-J-WS-081524 P3645-03 TB-02-081524

I certify that the data package is in compliance with the terms and conditions of the contract, both technically and for completeness, for other than the conditions detailed above. Release of the data contained in this hard copy data package has been authorized by the laboratory manager or his designee, as verified by the following signature.

Signature :		
Signature .	————— Date:	10/28/2024

NYDOH CERTIFICATION NO - 11376

NJDEP CERTIFICATION NO - 20012