

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## **Report of Analysis**

Client: Chemtech Consulting Group Date Collected: 09/03/24 Project: NJ Waste Water PT Date Received: 09/05/24 Client Sample ID: PT-SNTI-WP SDG No.: P3846 Lab Sample ID: P3846-03 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua. DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-31-5	Tin	1190	1	3.28	40.0	ug/L	10/17/24 12:30	10/17/24 14:37	EPA 200.7	7
7440-32-6	Titanium	86.7	1	9.18	40.0	ug/L	10/17/24 12:30	10/17/24 14:37	EPA 200.	7

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group4

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits