

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Chemtech Consulting Group Date Collected: 09/03/24 10:00

Project: NJ Waste Water PT Date Received: 09/05/24

Client Sample ID: PT-MIN1-WP SDG No.: P3848

Lab Sample ID: P3848-06 Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Bromide	8.90		1	0.034	2.00	mg/L		09/17/24 12:03	9056A
Chloride	338	OR	1	0.011	0.60	mg/L		09/17/24 12:03	9056A
Fluoride	1.40		1	0.057	0.40	mg/L		09/17/24 12:03	9056A
Sulfate	117	OR	1	0.032	3.00	mg/L		09/17/24 12:03	9056A
Sulfate	108	OR	1	0.41	5.00	mg/L		09/20/24 12:15	9038

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits