

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## **Report of Analysis**

Client:Chemtech Consulting GroupDate Collected:09/03/24 10:00Project:NJ Waste Water PTDate Received:09/05/24

Client Sample ID: PT-NUT3-WP SDG No.: P3848

Lab Sample ID: P3848-15 Matrix: WATER

% Solid: 0

Parameter	Conc. Qu	ıa. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	
Nitrite	1.50	1 0.011	0.60	mg/L		09/17/24 12:4	6 300.0	

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits