

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Chemtech Consulting Group Date Collected: 09/03/24 10:00 Project: NJ Waste Water PT Date Received: 09/05/24 Client Sample ID: PT-CL-WP SDG No.: P3848 Lab Sample ID: P3848-19 Matrix: Water % Solid: 0

Parameter	Conc. Qua	a. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Residual Chlorine	1.31	1 0.016	0.10	mg/L		09/16/24 16:36	SM 4500-Cl
							G 11

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits