

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **ENTACT** Date Collected: 09/17/24 11:40 Project: Date Received: North Point 09/18/24 Client Sample ID: WC-22A SDG No.: P4103 Lab Sample ID: P4103-01 Matrix: SOIL % Solid: 92.7

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigh	nt) Prep Date	Date Ana.	Ana Met.
Cyanide	0.047	U	1	0.047	0.26	mg/Kg	09/24/24 09:00	09/24/24 17:25	9012B
Hexavalent Chromium	0.085	U	1	0.085	0.43	mg/Kg	09/20/24 13:30	09/20/24 17:14	7196A
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		09/23/24 09:20	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits