

## Report of Analysis

Client:	ENTACT	Date Collected:	09/17/24 13:30
Project:	North Point	Date Received:	09/18/24
Client Sample ID:	WC-14-5-7.5B	SDG No.:	P4103
Lab Sample ID:	P4103-08	Matrix:	SOIL
		% Solid:	100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	9.33	H	1	0	0	pH		09/19/24 16:47	9045D
Ignitability	NO		1	0	0	oC		09/24/24 09:48	1030
Reactive Cyanide	0.0087	U	1	0.0087	0.050	mg/Kg	09/18/24 14:45	09/19/24 11:26	9012B
Reactive Sulfide	6.35	J	1	0.19	10.0	mg/Kg	09/23/24 08:50	09/23/24 11:20	9034

Comments: pH result reported at temperature 25.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits