

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Scheideler Excavating Co. Inc. Date Collected: 10/10/24 13:35 Project: Robbinsville Date Received: 10/10/24 Client Sample ID: SP-10 SDG No.: P4385 Lab Sample ID: P4385-20 Matrix: SOIL % Solid: 94.4

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigl	it) Prep Date	Date Ana.	Ana Met.
Cyanide	0.052	J	1	0.046	0.26	mg/Kg	10/14/24 08:30	10/14/24 13:41	9012B
Hexavalent Chromium	0.083	U	1	0.083	0.42	mg/Kg	10/11/24 08:45	10/11/24 12:18	7196A
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		10/14/24 10:30	9095B
pН	7.19	Н	1	0	0	pН		10/11/24 09:50	9045D
Trivalent Chromium	19.0		1	0.53	0.53	mg/Kg		10/18/24 15:11	6010D

Comments: pH result reported at temperature 20.5 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits