

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Aramark Uniforms Date Collected: 10/16/24 12:57 Project: Date Received: Monthly 2024 10/16/24 Client Sample ID: SDG No.: P4423 GRAB Lab Sample ID: P4423-01 Matrix: WATER % Solid: 0

| Parameter | Conc. Qua. | DF MDL | LOQ / CRQL | Units | Prep Date | Date Ana.      | Ana Met. |
|-----------|------------|--------|------------|-------|-----------|----------------|----------|
| TPH       | 42.0       | 1 0.40 | 5.00       | mg/L  |           | 10/17/24 09:30 | 1664A    |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits