

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 10/16/24 Project: Spring Valley 69-13kV Class H Date Received: 10/16/24 Client Sample ID: SDG No.: P4426 Lab Sample ID: P4426-17 Matrix: **SOIL** % Solid: 100 Level (low/med): low

Cas	Parameter	Conc.	Qua. DF MDL	LOQ / CRQL	Units(Dry W	eigh <b>f)</b> rep Date	Date Ana.	Ana Met.	Prep Met.
7439-92-1	Lead	7.53	1 0.15	0.60	mg/Kg	10/18/24 09:15	10/22/24 19:04	SW6010	SW3050

Color Before: Brown Clarity Before: Texture: Medium

Color After: Yellow Clarity After: Artifacts: N/A

Comments: Metals Group3

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits