

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

_

Report of Analysis

Client:	PSEG	Date Collected:	10/16/24
Project:	Spring Valley 69-13kV Class H	Date Received:	10/16/24
Client Sample ID:	PAD-10	SDG No.:	P4426
Lab Sample ID:	P4426-19	Matrix:	SOIL
Level (low/med):	low	% Solid:	100

Cas	Parameter	Conc.	Qua. DF MDL	LOQ / CRQL	Units(Dry W	/eigh P)rep Date	Date Ana.	Ana Met.	Prep Met.
7439-92-1	Lead	0.099	1 0.0010	0.0060	mg/Kg	10/18/24 09:15	10/22/24 20:50	SW6010	SW3050

Color Before: Brown Clarity Before: Texture: Medium

Color After: Yellow Clarity After: Artifacts: N/A

Comments: Metals Group3

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits