

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 10/21/24 10:30 Project: Cedar Grove Switching Station Date Received: 10/21/24 Client Sample ID: **ETGI-345** SDG No.: P4468 Lab Sample ID: P4468-05 Matrix: **SOIL** % Solid: 91.3

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigh	t) Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	0.44	U	1	0.086	0.44	mg/Kg	10/22/24 09:00	10/22/24 13:07	7196A
Ignitability	NO		1	0	0	oC		10/22/24 15:12	1030
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		10/22/24 13:52	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits