

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Holland Manufacturing Co. Date Collected: 10/22/24 12:00 Project: Pre Treatment Plant Date Received: 10/22/24 Client Sample ID: AERATION-TK-1 SDG No.: P4490 P4490-04 Lab Sample ID: Matrix: WATER % Solid:

Parameter	Conc. Qu	a. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TSS	5290	1 1.00	4.00	mg/L		10/22/24 15:0	00 SM 2540 D-15

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits