

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 10/23/24 11:48 Project: Bergen Point 69kV - 4KV-13KV Conversion Project OP Date Received: 10/23/24 Client Sample ID: BP-F22 SDG No.: P4508 Lab Sample ID: P4508-09 Matrix: **SOIL** 

% Solid: 90.8

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigh	nt) Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	0.44	U	1	0.087	0.44	mg/Kg	10/23/24 14:30	10/24/24 10:06	7196A
Ignitability	NO		1	0	0	oC		10/24/24 14:30	1030
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		10/24/24 12:42	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits