

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 10/23/24 11:39 Project: Somerset HQ Date Received: 10/23/24 Client Sample ID: 72-11986 SDG No.: P4516 Lab Sample ID: P4516-01 Matrix: **SOIL** % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	6.70	Н	1	0	0	pН		10/24/24 09:10	9045D
Ignitability	NO		1	0	0	oC		10/24/24 15:15	1030
Reactive Cyanide	0.050	U	1	0.0088	0.050	mg/Kg	10/25/24 13:45	10/25/24 16:22	9012B
Reactive Sulfide	1.59	J	1	0.19	10.0	mg/Kg	10/24/24 08:40	10/24/24 11:53	9034

Comments: pH result reported at temperature 23.3 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits