

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client:Lockwood, Kessler & Bartlett, Inc.Date Collected:10/23/24 10:05Project:Ansonia Landfill 2024Date Received:10/24/24

Client Sample ID: MW-1DL SDG No.: P4548
Lab Sample ID: P4548-01DL Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	110	D	50 0.55	30.0	mg/L		10/25/24 12:06	300.0

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits