

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Lockwood, Kessler & Bartlett, Inc. Date Collected: 10/23/24 11:00

Project: Ansonia Landfill 2024 Date Received: 10/24/24

Client Sample ID: MW-3DL SDG No.: P4548

Lab Sample ID: P4548-05DL Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ammonia as N	5.90	D	5	0.23	0.50	mg/L	10/28/24 08:40	10/28/24 14:41	SM 4500-NH3 B plus G-11
Chloride	230	D	100	1.10	60.0	mg/L		10/25/24 13:32	300.0

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits