

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Portal Partners Tri-Venture Date Collected: 10/25/24 11:15 Project: Amtrak Sawtooth Bridges 2024 Date Received: 10/25/24 Client Sample ID: **WB-305-BOT** SDG No.: P4578 Lab Sample ID: P4578-06 Matrix: **SOIL** % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.71	Н	1	0	0	pН		10/25/24 18:00	9045D
Ignitability	NO		1	0	0	oC		10/29/24 11:08	1030
Reactive Cyanide	0.0088	U	1	0.0088	0.050	mg/Kg	10/29/24 09:00	10/29/24 13:34	9012B
Reactive Sulfide	4.78	J	1	0.19	10.0	mg/Kg	10/26/24 09:30	10/26/24 12:10	9034

Comments: pH result reported at temperature 21.2 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits