

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900, Fax: 908 789 8922

Report of Analysis

Client: Tully Construction Co., Inc. Date Collected: 10/28/24

Project: Pitkin Yard Date Received: 10/28/24

Client Sample ID: PITKIN-COMP SDG No.: P4595

Lab Sample ID: P4595-02 Matrix: **TCLP**

% Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	34.8	U	1	34.8	100	ug/L	10/29/24 11:30	10/30/24 18:43	SW6010	SW3050
7440-39-3	Barium	1430		1	62.8	500	ug/L	10/29/24 11:30	10/30/24 18:43	SW6010	SW3050
7440-43-9	Cadmium	1.72	J	1	0.94	30.0	ug/L	10/29/24 11:30	10/30/24 18:43	SW6010	SW3050
7440-47-3	Chromium	13.0	J	1	6.60	50.0	ug/L	10/29/24 11:30	10/30/24 18:43	SW6010	SW3050
7439-92-1	Lead	342		1	35.1	60.0	ug/L	10/29/24 11:30	10/30/24 18:43	SW6010	SW3050
7439-97-6	Mercury	0.81	U	1	0.81	2.00	ug/L	10/29/24 14:55	10/30/24 16:27	SW7470A	
7782-49-2	Selenium	58.8	U	1	58.8	100	ug/L	10/29/24 11:30	10/30/24 18:43	SW6010	SW3050
7440-22-4	Silver	5.80	U	1	5.80	50.0	ug/L	10/29/24 11:30	10/30/24 18:43	SW6010	SW3050

Color Before: Colorless Clarity Before: Clear Texture: Color After: Colorless Clarity After: Clear Artifacts:

TCLP METALS Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits