

Surrogate Summary

SW-846

SDG No.: P4595

Client: Tully Construction Co., Inc.

Analytical Method: 8270E

Lab Sample ID	Client ID	Parameter	Spike (PPM)	Result (PPM)	Recovery (%)	Qual	Limits (%)	
							Low	High
P4594-05MS	BP-F17MS	Nitrobenzene-d5	100	68.3	68		18	107
		2-Fluorobiphenyl	100	65.7	66		20	109
		Terphenyl-d14	100	68.6	69		10	105
P4594-05MSD	BP-F17MSD	Nitrobenzene-d5	100	62.8	63		18	107
		2-Fluorobiphenyl	100	61.2	61		20	109
		Terphenyl-d14	100	61.7	62		10	105
P4595-01	PITKIN-COMP	Nitrobenzene-d5	100	46.2	46		18	107
		2-Fluorobiphenyl	100	49.3	49		20	109
		Terphenyl-d14	100	55.4	55		10	105
PB164497BL	PB164497BL	Nitrobenzene-d5	100	90.3	90		18	107
		2-Fluorobiphenyl	100	85.1	85		20	109
		Terphenyl-d14	100	87.9	88		10	105
PB164497BS	PB164497BS	Nitrobenzene-d5	100	90.3	90		18	107
		2-Fluorobiphenyl	100	87.2	87		20	109
		Terphenyl-d14	100	93.2	93		10	105