

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 10/28/24 08:40 Project: Harvey Switch Date Received: 10/28/24 Client Sample ID: RED-1-1 SDG No.: P4597 Lab Sample ID: P4597-03 Matrix: SOIL % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	6.32	Н	1	0	0	pН		10/28/24 17:05	9045D
Ignitability	NO		1	0	0	oC		10/30/24 12:08	1030
Reactive Cyanide	0.050	U	1	0.0088	0.050	mg/Kg	10/29/24 09:00	10/29/24 13:41	9012B
Reactive Sulfide	4.73	J	1	0.19	10.0	mg/Kg	10/30/24 08:45	10/30/24 12:40	9034

Comments: pH result reported at temperature 23.0 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits