

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Union Paving & Construction Company Date Collected: 10/31/24 12:50 Project: Rt. 10 Whippany Date Received: 10/31/24 Client Sample ID: TENNANT-PAD-2-3-STOCKPILE SDG No.: P4663 Lab Sample ID: P4663-02 Matrix: **SOIL**

% Solid: 90.9

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigh	nt) Prep Date	Date Ana.	Ana Met.
Cyanide	0.33		1	0.047	0.27	mg/Kg	11/01/24 14:00	11/04/24 12:09	9012B
Hexavalent Chromium	0.086	U	1	0.086	0.43	mg/Kg	11/04/24 11:00	11/04/24 14:54	7196A
Trivalent Chromium	16.2		1	0.55	0.55	mg/Kg		11/04/24 20:12	6010D

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits