

## LAB CHRONICLE

<b>OrderID:</b>	P4663	<b>OrderDate:</b>	10/31/2024 3:05:00 PM
<b>Client:</b>	Union Paving & Construction Company	<b>Project:</b>	Rt. 10 Whippany
<b>Contact:</b>	Gregory Butler	<b>Location:</b>	K41,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
<b>P4663-02</b>	<b>TENNANT-PAD-2-3-ST OCKPILE</b>	<b>SOIL</b>			<b>10/31/24</b>			<b>10/31/24</b>
			Herbicide	8151A		11/04/24	11/05/24	
			PCB	8082A		11/01/24	11/01/24	
			Pesticide-TCL	8081B		11/01/24	11/01/24	
			TPH GC	8015D		11/01/24	11/01/24	
			EPH_NF	NJEPH		11/01/24	11/02/24	
<b>P4663-04</b>	<b>RES-BUILDING-PAD-N O-11</b>	<b>SOIL</b>			<b>10/31/24</b>			<b>10/31/24</b>
			Herbicide	8151A		11/04/24	11/05/24	
			PCB	8082A		11/01/24	11/01/24	
			Pesticide-TCL	8081B		11/01/24	11/01/24	
			TPH GC	8015D		11/01/24	11/01/24	
			EPH_NF	NJEPH		11/01/24	11/02/24	
<b>P4663-06</b>	<b>RES-BUILDING-PAD-N O-3</b>	<b>SOIL</b>			<b>10/31/24</b>			<b>10/31/24</b>
			Herbicide	8151A		11/04/24	11/05/24	
			PCB	8082A		11/01/24	11/01/24	
			Pesticide-TCL	8081B		11/01/24	11/01/24	
			TPH GC	8015D		11/01/24	11/01/24	
			EPH_NF	NJEPH		11/01/24	11/02/24	
<b>P4663-08</b>	<b>RES-BUILDING-PAD-N O-2</b>	<b>SOIL</b>			<b>10/31/24</b>			<b>10/31/24</b>
			Herbicide	8151A		11/04/24	11/05/24	
			PCB	8082A		11/01/24	11/01/24	
			Pesticide-TCL	8081B		11/01/24	11/01/24	
			TPH GC	8015D		11/01/24	11/01/24	
			EPH_NF	NJEPH		11/01/24	11/02/24	