

Report of Analysis

Client:	Weston Solutions	Date Collected:	10/31/24 12:25
Project:	Ft Meade Tipton Airfield Parcel RI - PO 0111169	Date Received:	11/01/24
Client Sample ID:	TAPLPR-SED05-103124-00-T2	SDG No.:	P4672
Lab Sample ID:	P4672-05	Matrix:	SOIL
		% Solid:	83.9

Parameter	Conc.	Qua.	DF	MDL	LOD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
pH	6.53	H	1	0	0	0	pH		11/03/24 10:37	9045D
TOC	1820		1	8.00	50.0	250	mg/Kg		11/01/24 16:42	Lloyd Kahn

Comments: pH result reported at temperature 24.5 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits