

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 11/04/24 14:40

Project: CF- 613 East Rutherford and Wallington Date Received: 11/04/24

Client Sample ID: CF-613-COMP-17 SDG No.: P4711

Lab Sample ID: P4711-10 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	5.85	Н	1	0	0	pН		11/04/24 16:50	9045D
Ignitability	NO		1	0	0	oC		11/07/24 11:52	1030
Reactive Cyanide	0.012	J	1	0.0088	0.050	mg/Kg	11/06/24 12:50	11/06/24 15:34	9012B
Reactive Sulfide	4.73	J	1	0.19	10.0	mg/Kg	11/06/24 14:30	11/06/24 17:05	9034

Comments: pH result reported at temperature 22.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits