

LAB CHRONICLE

OrderID:	P4722	OrderDate:	11/5/2024 3:33:08 PM
Client:	Walsh Construction Company II, LLC	Project:	NYCDEP C547A - Shafts 17B-1 & 18B-1 Stage 2
Contact:	Kayla Timony	Location:	L23,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P4722-03	WC-1(0-6)	SOIL			11/05/24			11/05/24
			Mercury	7471B		11/07/24	11/07/24	
			Metals ICP-TAL	6010D		11/06/24	11/07/24	
			Metals ICP-TAL	6010D		11/06/24	11/08/24	
P4722-04	WC-1(0-6)	TCLP			11/05/24			11/05/24
			TCLP ICP Metals	6010D		11/07/24	11/08/24	
			TCLP Mercury	7470A		11/08/24	11/08/24	
P4722-05	WC-1(0-6)	Water			11/05/24			11/05/24
			SPLP ICP Metals	6010D		11/11/24	11/14/24	
			SPLP Mercury	7470A		11/11/24	11/12/24	
P4722-08	WC-2(0-6)	SOIL			11/05/24			11/05/24
			Mercury	7471B		11/07/24	11/07/24	
			Metals ICP-TAL	6010D		11/06/24	11/07/24	
P4722-09	WC-2(0-6)	TCLP			11/05/24			11/05/24
			TCLP ICP Metals	6010D		11/07/24	11/08/24	
			TCLP Mercury	7470A		11/08/24	11/08/24	
P4722-10	WC-2(0-6)	Water			11/05/24			11/05/24
			SPLP ICP Metals	6010D		11/11/24	11/14/24	
			SPLP Mercury	7470A		11/11/24	11/12/24	
P4722-13	WC-3(0-6)	SOIL			11/05/24			11/05/24
			Mercury	7471B		11/07/24	11/07/24	
			Metals ICP-TAL	6010D		11/06/24	11/07/24	
P4722-14	WC-3(0-6)	TCLP			11/05/24			11/05/24
			TCLP ICP Metals	6010D		11/07/24	11/08/24	
			TCLP Mercury	7470A		11/08/24	11/08/24	

LAB CHRONICLE

P4722-15	WC-3(0-6)	Water			11/05/24		11/05/24
			SPLP ICP Metals	6010D		11/11/24	11/14/24
			SPLP Mercury	7470A		11/11/24	11/12/24
