

Matrix Spike/Matrix Spike Duplicate Summary

SW-846

SDG No.: P4722

Client: Walsh Construction Company II, LLC

Analytical Method: 8081B

DataFile : PL092984.D

Lab Sample ID:	Parameter	Spike	Sample Result	Result	Units	Rec Qual	RPD Qual	Low	Limits High	RPD
Client Sample ID: WB-307-SB02MS										
P4718-03MS	gamma-BHC (Lindane)	5	0	4.90	ug/L	98		60	152	
	Heptachlor	5	0	5.40	ug/L	108		56	147	
	Heptachlor epoxide	5	0	5.30	ug/L	106		77	143	
	Endrin	5	0	5.20	ug/L	104		76	144	
	Methoxychlor	5	0	4.80	ug/L	96		70	142	