

LAB CHRONICLE

OrderID:	P4722	OrderDate:	11/5/2024 3:33:08 PM
Client:	Walsh Construction Company II, LLC	Project:	NYCDEP C547A - Shafts 17B-1 & 18B-1 Stage 2
Contact:	Kayla Timony	Location:	L23,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P4722-04	WC-1(0-6)	TCLP	TCLP BNA	8270E	11/05/24	11/07/24	11/08/24	11/05/24
P4722-09	WC-2(0-6)	TCLP	TCLP BNA	8270E	11/05/24	11/07/24	11/08/24	11/05/24
P4722-14	WC-3(0-6)	TCLP	TCLP BNA	8270E	11/05/24	11/07/24	11/08/24	11/05/24