

LAB CHRONICLE

OrderID:	P4722	OrderDate:	11/5/2024 3:33:08 PM
Client:	Walsh Construction Company II, LLC	Project:	NYCDEP C547A - Shafts 17B-1 & 18B-1 Stage 2
Contact:	Kayla Timony	Location:	L23,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
P4722-02	WC-1(3.5)	TCLP	TCLP VOA	8260D	11/05/24		11/08/24	11/05/24
P4722-05	WC-1(0-6)	Water	SPLP VOA	8260D	11/05/24		11/13/24	11/05/24
P4722-07	WC-2(4)	TCLP	TCLP VOA	8260D	11/05/24		11/11/24	11/05/24
P4722-10	WC-2(0-6)	Water	SPLP VOA	8260D	11/05/24		11/13/24	11/05/24
P4722-12	WC-3(3)	TCLP	TCLP VOA	8260D	11/05/24		11/11/24	11/05/24
P4722-15	WC-3(0-6)	Water	SPLP VOA	8260D	11/05/24		11/13/24	11/05/24
P4722-16	WC-1(5.5)	TCLP	TCLP VOA	8260D	11/05/24		11/11/24	11/05/24
P4722-18	WC-2(2)	TCLP	TCLP VOA	8260D	11/05/24		11/11/24	11/05/24
P4722-20	WC-3(5)	TCLP	TCLP VOA	8260D	11/05/24		11/11/24	11/05/24