

Surrogate Summary

SDG No.: P4722

Client: Walsh Construction Company II, LLC

Analytical Method: SW8260D

Lab Sample ID	Client ID	Parameter	Spike	Result	RecoveryQual	Limits	
						Low	High
P4722-05	WC-1(0-6)	1,2-Dichloroethane-d4	50	48.3	97	74	125
		Dibromofluoromethane	50	47.8	96	75	124
		Toluene-d8	50	45.8	92	86	113
		4-Bromofluorobenzene	50	46.8	94	77	121
P4722-10	WC-2(0-6)	1,2-Dichloroethane-d4	50	47.9	96	74	125
		Dibromofluoromethane	50	48.4	97	75	124
		Toluene-d8	50	45.9	92	86	113
		4-Bromofluorobenzene	50	46.3	93	77	121
P4722-15	WC-3(0-6)	1,2-Dichloroethane-d4	50	46.5	93	74	125
		Dibromofluoromethane	50	48.3	97	75	124
		Toluene-d8	50	45.9	92	86	113
		4-Bromofluorobenzene	50	44.8	90	77	121

Surrogate Summary

SDG No.: P4722

Client: Walsh Construction Company II, LLC

Analytical Method: SW8260-Low

Lab Sample ID	Client ID	Parameter	Spike	Result	RecoveryQual	Limits	
						Low	High
VN1113WBL01	VN1113WBL01	1,2-Dichloroethane-d4	50	49.5	99	74	125
		Dibromofluoromethane	50	50.0	100	75	124
		Toluene-d8	50	46.6	93	86	113
		4-Bromofluorobenzene	50	45.8	92	77	121
VN1113WBS01	VN1113WBS01	1,2-Dichloroethane-d4	50	46.4	93	74	125
		Dibromofluoromethane	50	49.9	100	75	124
		Toluene-d8	50	49.2	98	86	113
		4-Bromofluorobenzene	50	51.2	102	77	121
VN1113WBSD0	VN1113WBSD01	1,2-Dichloroethane-d4	50	45.4	91	74	125
		Dibromofluoromethane	50	48.6	97	75	124
		Toluene-d8	50	47.8	96	86	113
		4-Bromofluorobenzene	50	51.0	102	77	121