

Report of Analysis

Client:	PSEG	Date Collected:	11/06/24 10:46
Project:	Bergen Point 69kV - 4KV-13KV Conversion Project OP	Date Received:	11/06/24
Client Sample ID:	TP-14	SDG No.:	P4739
Lab Sample ID:	P4739-04	Matrix:	SOIL
		% Solid:	100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.12	H	1	0	0	pH		11/06/24 17:15	9045D
Ignitability	NO		1	0	0	oC		11/09/24 09:38	1030
Reactive Cyanide	0.050	U	1	0.0087	0.050	mg/Kg	11/11/24 10:00	11/11/24 15:21	9012B
Reactive Sulfide	3.16	J	1	0.19	10.0	mg/Kg	11/07/24 13:50	11/07/24 17:40	9034

Comments: pH result reported at temperature 24.7 °C

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements
 H = Sample Analysis Out Of Hold Time

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits