

Duplicate Sample Summary

Client: Tully Environmental, Inc Project: Transfer Station-SPDES Client ID: 001-WILLETS-BLVD(SEP)DUP	SDG No.: P4757 Sample ID: P4757-01 Percent Solids for Spike Sample: 0
---	--

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
TSS	mg/L	+/-5	48.0		48.7		1	1.45		11/08/2024