

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Tully Environmental, Inc Date Collected: 11/06/24 Project: Transfer Station-SPDES Date Received: 11/07/24 Client Sample ID: 002-35TH-AVE(SEP) SDG No.: P4757 Lab Sample ID: P4757-02 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua. DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-50-8	Copper	93.4	1	1.52	10.0	ug/L	11/08/24 09:00	11/08/24 15:16	EPA 200.7	
7439-89-6	Iron	4450	1	12.4	50.0	ug/L	11/08/24 09:00	11/08/24 15:16	EPA 200.7	
7439-92-1	Lead	14.3	1	1.57	6.00	ug/L	11/08/24 09:00	11/08/24 15:16	EPA 200.7	

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group 10

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits