

Initial and Continuing Calibration Verification

Client: VERINA CONSULTING GROUP, LLC

SDG No.: P4763

Project: Rotor Clip - PO# 5183.0001

RunNo.: LB133358

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Ammonia as N	mg/L	0.99	1	99	90-110	11/08/2024
Sample ID: CCV1 Ammonia as N	mg/L	1	1	100	90-110	11/08/2024
Sample ID: CCV2 Ammonia as N	mg/L	0.97	1	97	90-110	11/08/2024
Sample ID: CCV3 Ammonia as N	mg/L	1	1	100	90-110	11/08/2024
Sample ID: CCV4 Ammonia as N	mg/L	1	1	100	90-110	11/08/2024
Sample ID: CCV5 Ammonia as N	mg/L	0.96	1	96	90-110	11/08/2024

Initial and Continuing Calibration Verification

Client: VERINA CONSULTING GROUP, LLC

SDG No.: P4763

Project: Rotor Clip - PO# 5183.0001

RunNo.: LB133363

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Residual Chlorine	mg/L	0.407	0.4	102	90-110	11/08/2024
Sample ID: CCV1 Residual Chlorine	mg/L	0.397	0.4	99	90-110	11/08/2024
Sample ID: CCV2 Residual Chlorine	mg/L	0.397	0.4	99	90-110	11/08/2024

Initial and Continuing Calibration Verification

Client: VERINA CONSULTING GROUP, LLC

SDG No.: P4763

Project: Rotor Clip - PO# 5183.0001

RunNo.: LB133363

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
---------	-------	--------	------------	---------------	---------------------------	------------------