

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: P4765

Project: Linden Generating Station - LRSA

RunNo.: LB133358

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Ammonia as N	mg/L	0.99	1	99	90-110	11/08/2024
Sample ID: CCV1 Ammonia as N	mg/L	1	1	100	90-110	11/08/2024
Sample ID: CCV2 Ammonia as N	mg/L	0.97	1	97	90-110	11/08/2024
Sample ID: CCV3 Ammonia as N	mg/L	1	1	100	90-110	11/08/2024
Sample ID: CCV4 Ammonia as N	mg/L	1	1	100	90-110	11/08/2024
Sample ID: CCV5 Ammonia as N	mg/L	0.96	1	96	90-110	11/08/2024

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: P4765

Project: Linden Generating Station - LRSA

RunNo.: LB133431

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV COD	mg/L	51.341	50	103	95-105	10/14/2024
Sample ID: CCV1 COD	mg/L	48.325	50	97	95-105	11/13/2024
Sample ID: CCV2 COD	mg/L	50.336	50	101	95-105	11/13/2024
Sample ID: CCV3 COD	mg/L	48.325	50	97	95-105	11/13/2024

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: P4765

Project: Linden Generating Station - LRSA

RunNo.: LB133455

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV						
Field pH		pH	7	7	100	90-110	11/07/2024
Sample ID:	CCV1						
Field pH		pH	7	7	100	90-110	11/07/2024
Sample ID:	CCV2						
Field pH		pH	7.00	7	100	90-110	11/07/2024

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: P4765

Project: Linden Generating Station - LRSA

RunNo.: LB133455

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
---------	-------	--------	------------	---------------	---------------------------	------------------