

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Date Collected: 11/04/24 13:00

Project: 540 Degraw St, Brooklyn, NY - E9309 Date Received: 11/08/24

Client Sample ID: WC-TA1-01-C SDG No.: P4799

Lab Sample ID: P4799-11 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	12.0	Н	1	0	0	pН		11/11/24 16:45	9045D
Ignitability	NO		1	0	0	oC		11/13/24 15:17	1030
Reactive Cyanide	0.0087	U	1	0.0087	0.050	mg/Kg	11/11/24 12:00	11/11/24 15:36	9012B
Reactive Sulfide	1.59	J	1	0.19	10.0	mg/Kg	11/13/24 09:15	11/13/24 13:40	9034

Comments: pH result reported at temperature 24.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits