

Report of Analysis

Client:ENTACTProject:540 Degraw St, Brooklyn, NY - E9309Client Sample ID:WC-TA1-02-C						Date Collected:		11/05/24 13:00	
]	Date Received:	11/08/24	
						SDG No.:		P4799	
Lab Sample ID:	P4799-15					Matrix:		SOIL	
						(% Solid:	100	
Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	12.0	Н	1	0	0	pН		11/11/24 16:50	9045D
Ignitability	NO		1	0	0	oC		11/13/24 15:25	1030
Reactive Cyanide	0.0088	U	1	0.0088	0.050	mg/Kg	11/11/24 12:00	11/11/24 15:36	9012B
Reactive Sulfide	1.59	J	1	0.19	10.0	mg/Kg	11/13/24 09:15	11/13/24 13:43	9034

Comments: pH result reported at temperature 24.3 °C

- U = Not Detected
- LOQ = Limit of Quantitation
- MDL = Method Detection Limit
- LOD = Limit of Detection
- D = Dilution
- Q = indicates LCS control criteria did not meet requirements
- H = Sample Analysis Out Of Hold Time

- J = Estimated Value
- B = Analyte Found in Associated Method Blank

- E = Indicates the reported value is estimated because of the presence of interference.
- OR = Over Range
- N =Spiked sample recovery not within control limits

^{* =} indicates the duplicate analysis is not within control limits.