

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

## **Report of Analysis**

Client: ENTACT

Project: North Point

Client Sample ID: EX-9-TPH-21

Lab Sample ID: P4839-13

Analytical Method: 8015D DRO

Sample Wt/Vol: 30.02 Units: g

Soil Aliquot Vol: uL

Extraction Type:

FG014845.D

GPC Factor: PH:

5

Prep Method: SW3541

File ID/Qc Batch: Dilution:

Prep Date

Date Analyzed

Date Collected:

Date Received:

SDG No.:

Matrix:

% Solid:

Final Vol:

Injection Volume:

Test:

11/13/24

11/13/24

P4839

**SOIL** 

80.6

Prep Batch ID

Diesel Range Organics

Decanted:

mL

11/14/24 13:15 11/18/24 12:00 PB164995

CAS Number	Parameter	Conc.	Qualifier	MDL	LOQ / CRQL	Units(Dry Weight)
TARGETS DRO	DRO	117000		1150	10300	ug/kg
<b>SURROGATES</b> 16416-32-3	Tetracosane-d50	2.68		37 - 130	67%	SPK: 20

## Comments:

U = Not Detected

LOO = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

\* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit