

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: ENTACT Date Collected:

Project: North Point Date Received:

Client Sample ID: VBF1115S1 SDG No.: P4839

Lab Sample ID: VBF1115S1 Matrix: SOIL

Analytical Method: 8015D GRO % Solid: 100 Decanted:

Sample Wt/Vol: 5 Units: g Final Vol: 5 mL

Soil Aliquot Vol: uL Test: Gasoline Range Organics

Extraction Type: Injection Volume:

GPC Factor: PH:

Prep Method:

File ID/Qc Batch: Dilution: Date Analyzed Prep Batch ID

FB031201.D 1 11/15/24 7:51 FB111524

CAS Number	Parameter	Conc.	Qualifier MDL	LOQ / CRQL	Units
SURROGATES					
98-08-8	Alpha, Alpha, Alpha-Trifluoroto	19.1	50 - 150	95%	SPK: 20

Comments:

U = Not Detected

LOO = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit