

CLIENT INFORMATION

REPORT TO BE SENT TO:

COMPANY: Tully Environmental
 ADDRESS: 57 Seaview Blvd
 CITY: Pt Washington STATE: NY ZIP: 11050
 ATTENTION: D Devoe
 PHONE: 718 446 7000 FAX: 718 458 5199

CLIENT PROJECT INFORMATION

PROJECT NAME: Transfer Station SPAS
 PROJECT NO.: 242113 LOCATION:
 PROJECT MANAGER:
 e-mail:
 PHONE: FAX:

CLIENT BILLING INFORMATION

BILL TO: Same PO#:
 ADDRESS:
 CITY STATE: ZIP:
 ATTENTION: PHONE:

ANALYSIS

DATA TURNAROUND INFORMATION

FAX (RUSH) _____ DAYS*
 HARDCOPY (DATA PACKAGE): _____ DAYS*
 EDD: _____ DAYS*

*TO BE APPROVED BY CHEMTECH

STANDARD HARDCOPY TURNAROUND TIME IS 10 BUSINESS DAYS

DATA DELIVERABLE INFORMATION

☐ Level 1 (Results Only) ☐ Level 4 (QC + Full Raw Data)
☐ Level 2 (Results + QC) ☐ NJ Reduced ☐ US EPA CLP
☐ Level 3 (Results + QC) ☐ NYS ASP A ☐ NYS ASP B
 + Raw Data ☐ Other _____
☐ EDD FORMAT _____

1 Cu Fe Pb
 2 BOD 5
 3 TSS
 4 Hg 163122
 5 BTEX
 6 D&G Ammonia
 7
 8
 9

PRESERVATIVES

COMMENTS

CHEMTECH SAMPLE ID	PROJECT SAMPLE IDENTIFICATION	SAMPLE MATRIX	SAMPLE TYPE		SAMPLE COLLECTION		# OF BOTTLES										← Specify Preservatives A-HCl D-NaOH B-HNO3 E-ICE C-H2SO4 F-OTHER
			COMP	GRAB	DATE	TIME		1	2	3	4	5	6	7	8	9	
1.	001 Willets Pt Blvd (Nov)	W		X	11/13	3pm		X	X	X	X	X	X				
2.	002 35th Ave (Nov)	W		X	11/13	3pm		X	X	X	X	X	X				
3.																	
4.																	
5.																	
6.																	
7.																	
8.																	
9.																	

SAMPLE CUSTODY MUST BE DOCUMENTED BELOW EACH TIME SAMPLES CHANGE POSSESSION INCLUDING COURIER DELIVERY

QUISHED BY SAMPLER: D Devoe	DATE/TIME: 11/13/24	RECEIVED BY: 1. [Signature]	Conditions of bottles or coolers at receipt: ☐ COMPLIANT ☐ NON COMPLIANT ☐ COOLER TEMP 4.0 °C
ISHED BY SAMPLER:	DATE/TIME: 1049	RECEIVED BY: 2. [Signature]	Comments: 7A Can #1
IED BY SAMPLER:	DATE/TIME: 11-14-24	RECEIVED BY: 3. [Signature]	Page ____ of ____
			CLIENT: ☐ Hand Delivered ☐ Other _____ CHEMTECH: ☐ Picked Up ☐ Field Sampling
			Shipment Complete ☐ YES ☐ NO